## **Quality Inspection List**

This summary supports the production-release quality gate. Refer to the quality register for sampling-plan references. Use this extract to coordinate sign-off with the QA manager. This section details quality requirements and test points for the batch. This checklist captures quality inspection points and sampling levels. Ensure all non-conforming marks are clearly documented.

Product ID	SL-430M	Customer ID	FRANCE
Item Description	Control Panel Mount		

	Inspection Checklist Points	Sampling Level	Defe	ct Clas	S		Comments
Α	Item Specs		С	М	m	Н	
1	Product doesn't power on	Level I				V	Critical impact
2	Rubber texture or glossiness mismatch		V	V			
3	Instruction manual is missing or damaged	Level II	V		V		Critical impact
4	Functionality test failed	Level III					Needs review
5	Hinges loose	Level I	٧		V		Needs review
6	Wood splinter or sharp point on product				V	V	
7	Missing distributor information	Level II	V	V			
8	Packaging does not match signed sample	Level III					Needs review
9	Shipping mark is illegible or missing						Needs review
10	Missing logo or warning label		V	V			Needs review
11	Sharp edges on plastic components	Level I			V	V	Critical impact

Supervised by: Date:
----------------------