The equipment log below includes fault codes and corrective notes. Confirm that service intervals follow the preventive schedule. Below is the summary of service actions and downtimes for each machine. Check that all downtime events are properly categorized and logged. Ensure all safety checks were completed during servicing.

## Spare Parts Used:

Part Name	Part No.	Qty Used
Switch Assembly	P-5380	1

Unit Code	Equipment	Туре	Operator	Downtime	Last Check	Area	Notes
MC-285	Conveyor	Corrective	Peter	2.7	2023-10-16	Replaced	
	Belt		Schmidt			fuse (5A).	
MC-282	Assembly	Preventive	Laura Rossi	2.0	2023-09-21	Alignment of	
	Robot					hinges	
						adjusted.	
MC-263	Paint Booth	Corrective	Carlos	3.6	2024-03-01	Worn gasket	
			Garcia			replaced.	
MC-222	Assembly	Inspection	Peter	1.5	2025-01-21	Sensor	
	Robot		Schmidt			recalibrated.	
MC-215	Packaging	Corrective	Laura Rossi	2.8	2024-06-09	Wooden	
	Line					pallet	
						checked.	
MC-292	CNC Milling	Preventive	Anna	2.2	2023-07-26	Wooden	
	Machine		Nowak			pallet	
						checked.	

Authorized by:	Peter Schmidt
Operator:	Carlos Garcia