Machine Log Summary

Performed On: 2024-12-10

Authorized by:	Laura Rossi
Operator:	Carlos Garcia

Ensure all safety checks were completed during servicing. The equipment log below includes fault codes and corrective notes. This service summary supports the reliability engineering review. This maintenance extract is prepared for compliance audit trails. Check that all downtime events are properly categorized and logged.

Section A:

Machine ID	MC-280	MC-294	MC-231	MC-239	MC-284	MC-217
Machine	Lathe	Plasma Cutter	CNC Milling	Paint Booth	Lathe	Packaging
			Machine			Line
Service Type	Corrective	Preventive	Corrective	Corrective	Preventive	Inspection
Technician	Laura Rossi	Laura Rossi	Laura Rossi	Peter Schmidt	Carlos Garcia	Anna Nowak
Duration	3.0	1.7	2.7	1.7	3.8	3.0
Notes	Switch	Refilled oil	Switch	Worn gasket		
	contacts	(HLP 46).	contacts	replaced.		
	cleaned.		cleaned.			

Section B:

Machine ID	MC-294	MC-226	MC-290	MC-280	MC-274	MC-231
Machine	Plasma Cutter	Plasma Cutter	Plasma Cutter	Lathe	Laser Cutter	CNC Milling Machine
Service Type	Inspection	Inspection	Inspection	Corrective	Preventive	Preventive
Technician	Jan Kowalski	Peter Schmidt	Anna Nowak	Anna Nowak	Carlos Garcia	Jan Kowalski
Duration	3.6	3.8	3.0	1.7	2.5	3.2
Notes	Tightened	Tightened	Tightened	Replaced	Changed oil	Refilled oil
	loose bolts.	loose bolts.	loose bolts.	coolant.	and filters.	(HLP 46).

Uptime (%)	Error Count	Comments
92.14%	4	Bolt tightened