The following entries detail preventive and corrective maintenance tasks. Check that all downtime events are properly categorized and logged. Below is the summary of service actions and downtimes for each machine. Entries include work orders, technician assignments, and part changes. Confirm that service intervals follow the preventive schedule. Ensure all safety checks were completed during servicing.

## Spare Parts Used:

Part Name	Part No.	Qty Used
Switch Assembly	P-5558	1
Switch Assembly	P-4856	3
Switch Assembly	P-6867	4
Li-Ion Battery Pack	P-1455	4

Unit Code	Equipment	Туре	Technician	Downtime	Previous Service	Site	Comments
MC-247	Lathe	Preventive	Jan Kowalski	3.2	2025-05-08	Alignment of hinges adjusted.	
MC-249	Plasma Cutter	Preventive	Laura Rossi	2.2	2025-02-03	Sensor recalibrated.	
MC-266	Assembly Robot	Preventive	Peter Schmidt	2.0	2024-09-14	Replaced coolant.	
MC-268	Hydraulic Press	Preventive	Peter Schmidt	2.3	2023-10-30	Refilled oil (HLP 46).	
MC-215	Paint Booth	Inspection	Peter Schmidt	3.3	2024-06-16	Li-Ion battery pack serviced.	

Signed off:	Peter Schmidt
Performed by:	Peter Schmidt