## Maintenance Checklist Report #9541543

Date: 2024-09-10

Unit Code	Machine	Service Type	Technician	Duration	Area	Notes
MC-202	Laser Cutter	Preventive	Carlos Garcia	2.4	Plant 3A	Sensor recalibrated.
MC-254	Conveyor Belt	Corrective	Anna Nowak	2.1	Plant 2B	Tightened loose bolts.
MC-270	Assembly Robot	Corrective	Peter Schmidt	2.4	Plant 3A	Sensor recalibrated.
MC-284	Laser Cutter	Corrective	Peter Schmidt	1.6	Plant 3A	Wooden pallet checked.
MC-260	Plasma Cutter	Preventive	Anna Nowak	2.0	Plant 2B	No issues found.
MC-275	Laser Cutter	Corrective	Peter Schmidt	2.4	Plant 3A	Wooden pallet checked.
MC-239	CNC Milling Machine	Inspection	Anna Nowak	1.5	Plant 3A	Li-lon battery pack serviced.
MC-205	Conveyor Belt	Preventive	Jan Kowalski	3.3	Plant 1C	Refilled oil (HLP 46).
MC-212	Paint Booth	Corrective	Carlos Garcia	4.0	Plant 1C	Alignment of hinges adjusted.

Archive this summary in the CMMS for future reference. Record any spare parts usage for inventory adjustment. All maintenance durations are recorded for performance metrics. No critical faults were found during the latest inspection. This log summary supports the asset-management dashboard. Ensure that each service entry has the required approvals.

Lubrication Checked	No
Calibration Verified	No
Emergency Stop Tested	N/A

Approved by:	Serviced by: