Equipment Record Report

Performed On: 2024-10-30

Authorized by:	Carlos Garcia
Operator:	Laura Rossi

Entries include work orders, technician assignments, and part changes. Check that all downtime events are properly categorized and logged. This maintenance extract is prepared for compliance audit trails. This service summary supports the reliability engineering review. Refer to the maintenance register for detailed service histories.

Section A:

Machine ID	MC-241	MC-277	MC-210	MC-285	MC-246	MC-217
Machine	Paint Booth	Paint Booth	Assembly Robot	Paint Booth	Packaging Line	Lathe
Туре	Inspection	Corrective	Preventive	Corrective	Preventive	Corrective
Technician	Carlos Garcia	Carlos Garcia	Anna Nowak	Carlos Garcia	Peter Schmidt	Laura Rossi
Downtime	2.3	2.8	3.5	2.5	3.4	2.7
Comments	Calibration check OK.	Li-lon battery pack serviced.		Alignment of hinges adjusted.	Calibration check OK.	Tightened loose bolts.

Section B:

Machine ID	MC-210	MC-285	MC-246	MC-217	MC-241	MC-277
Machine	Assembly Robot	Paint Booth	Packaging Line	Lathe	Paint Booth	Paint Booth
Туре	Preventive	Preventive	Preventive	Corrective	Corrective	Preventive
Technician	Carlos Garcia	Carlos Garcia	Laura Rossi	Jan Kowalski	Peter Schmidt	Anna Nowak
Downtime	1.6	3.0	2.4	2.4	2.8	2.3
Comments	Tightened loose bolts.	Replaced fuse (5A).	Changed oil and filters.	Refilled oil (HLP 46).	Wooden pallet checked.	

Maintenance notes are archived for compliance audits. No critical faults were found during the latest inspection. Overall equipment condition is satisfactory post-maintenance. All maintenance tasks have been completed as per schedule. Confirm that all corrective actions were properly closed out.

Uptime (%)	Error Count	Notes
97.45%	5	Replaced filter