This section captures equipment status and any maintenance observations. The following entries detail preventive and corrective maintenance tasks. Below is the summary of service actions and downtimes for each machine. Ensure all safety checks were completed during servicing.

## Spare Parts Used:

Part Name	Part No.	Qty Used
Oil Filter	P-6390	1
Switch Assembly	P-6793	3
Switch Assembly	P-3828	5

Unit Code	Machine	Service Type	Operator	Duration	Previous Service	Site	Comments
MC-288	Plasma Cutter	Preventive	Jan Kowalski	2.7	2025-05-06	Tightened loose bolts.	
MC-213	Assembly Robot	Preventive	Carlos Garcia	3.1	2024-06-15	Sensor recalibrated.	
MC-274	Laser Cutter	Preventive	Jan Kowalski	1.8	2024-11-24	Sensor recalibrated.	
MC-295	Plasma Cutter	Corrective	Carlos Garcia	3.5	2025-02-09	Tightened loose bolts.	
MC-258	CNC Milling Machine	Corrective	Carlos Garcia	3.0	2024-05-20	Wooden pallet checked.	
MC-292	Lathe	Corrective	Peter Schmidt	2.2	2025-04-15	Calibration check OK.	
MC-207	Laser Cutter	Inspection	Carlos Garcia	2.2	2024-02-27	Sensor recalibrated.	
MC-294	CNC Milling Machine	Corrective	Anna Nowak	2.4	2024-04-05	Wooden pallet checked.	

Signed off:	Jan Kowalski
Performed by:	Laura Rossi