Machine Log Summary

Performed On: 2024-05-23

Authorized by:	Carlos Garcia
Operator:	Laura Rossi

Check that all downtime events are properly categorized and logged. Please review this log for recent service dates, types, and remarks. Confirm that service intervals follow the preventive schedule. Use this summary to forecast parts replacement and resource needs. This maintenance extract is prepared for compliance audit trails. Use this record to plan upcoming upkeep and repairs.

Section A:

Unit Code	MC-298	MC-292	MC-201	MC-255	MC-230	MC-248
Machine	Assembly	Lathe	CNC Milling	Lathe	Laser Cutter	Lathe
	Robot		Machine			
Туре	Corrective	Preventive	Corrective	Preventive	Inspection	Preventive
Technician	Peter Schmidt	Jan Kowalski	Peter Schmidt	Carlos Garcia	Peter Schmidt	Peter Schmidt
Downtime	3.2	1.6	3.7	3.3	3.8	2.1
Comments	Sensor	Li-Ion battery	Wooden pallet	Replaced	Li-lon battery	Worn gasket
	recalibrated.	pack serviced.	checked.	coolant.	pack serviced.	replaced.

Section B:

Unit Code	MC-298	MC-230	MC-292	MC-245	MC-248	MC-201
Machine	Assembly	Laser Cutter	Lathe	Hydraulic	Lathe	CNC Milling
	Robot			Press		Machine
Туре	Corrective	Preventive	Preventive	Preventive	Inspection	Preventive
Technician	Laura Rossi	Carlos Garcia	Laura Rossi	Peter Schmidt	Anna Nowak	Laura Rossi
Downtime	3.0	3.6	4.0	1.5	3.5	3.6
Comments	No issues found.		Sensor recalibrated.	Switch contacts cleaned.	Changed oil and filters.	Wooden pallet checked.

All maintenance durations are recorded for performance metrics. Use this closure note to update the maintenance KPI tracker.

Uptime (%)	Error Count	Comments
98.44%	0	Replaced filter