Machine Log Summary #2672067

Date: 2025-07-09

Machine ID	Equipment	Service Type	Technician	Duration	Site	Comments
MC-241	Packaging Line	Preventive	Carlos Garcia	2.5	Plant 2B	Replaced
						coolant.
MC-205	Laser Cutter	Inspection	Anna Nowak	2.6	Plant 3A	Refilled oil (HLP
						46).
MC-211	Lathe	Corrective	Jan Kowalski	1.6	Plant 2B	Replaced
						coolant.
MC-203	Hydraulic Press	Preventive	Carlos Garcia	1.9	Plant 3A	No issues
						found.
MC-269	Assembly	Inspection	Carlos Garcia	3.9	Plant 2B	Calibration
	Robot					check OK.

Flag any recurring issues for root-cause investigation. All maintenance durations are recorded for performance metrics. Maintenance notes are archived for compliance audits. Check remaining life-cycles of key components from this report. This log summary supports the asset-management dashboard. Service summaries have been forwarded to the engineering team.

Lubrication Checked	N/A
Calibration Verified	Yes
Emergency Stop Tested	N/A

Approved by:	Serviced by: