Use this record to plan upcoming upkeep and repairs. This log records all maintenance activities performed on the equipment. Ensure all safety checks were completed during servicing. This service summary supports the reliability engineering review. Check that all downtime events are properly categorized and logged.

Spare Parts Used:

Part Name	Part No.	Qty Used
Sensor Module	P-9268	2

Unit Code	Equipment	Service Type	Technician	Downtime	Previous Service	Area	Notes
MC-242	Plasma Cutter	Preventive	Laura Rossi	3.4	2025-07-07	Switch contacts cleaned.	
MC-236	Hydraulic Press	Preventive	Carlos Garcia	1.7	2024-03-25	Changed oil and filters.	
MC-291	Hydraulic Press	Corrective	Peter Schmidt	2.0	2024-12-16	Replaced coolant.	
MC-250	Hydraulic Press	Preventive	Carlos Garcia	2.4	2023-07-22	Worn gasket replaced.	
MC-283	Lathe	Inspection	Carlos Garcia	2.6	2024-03-03	Li-lon battery pack serviced.	
MC-275	Lathe	Inspection	Jan Kowalski	3.0	2025-01-02	Refilled oil (HLP 46).	

Approved by:	Laura Rossi
Serviced by:	Peter Schmidt