Maintenance Checklist Report #3112018

Date: 2024-05-06

Unit Code	Machine	Туре	Operator	Downtime	Site	Notes
MC-260	Laser Cutter	Preventive	Carlos Garcia	1.6	Plant 3A	Calibration check OK.
MC-244	Lathe	Preventive	Jan Kowalski	2.9	Plant 3A	Wooden pallet checked.
MC-227	Plasma Cutter	Inspection	Jan Kowalski	2.4	Plant 2B	Replaced fuse (5A).
MC-280	CNC Milling Machine	Preventive	Laura Rossi	4.0	Plant 3A	Changed oil and filters.
MC-238	Plasma Cutter	Corrective	Anna Nowak	2.0	Plant 2B	Worn gasket replaced.
MC-233	Plasma Cutter	Preventive	Peter Schmidt	3.8	Plant 3A	Refilled oil (HLP 46).
MC-213	Assembly Robot	Corrective	Carlos Garcia	2.8	Plant 3A	Tightened loose bolts.
MC-242	Plasma Cutter	Preventive	Carlos Garcia	3.7	Plant 1C	No issues found.
MC-257	Paint Booth	Inspection	Anna Nowak	3.8	Plant 1C	No issues found.
MC-223	Paint Booth	Corrective	Carlos Garcia	2.9	Plant 2B	Replaced coolant.

Ensure next preventive service is scheduled according to plan. Refer to remarks for any follow-up actions or parts replacements. Ensure that each service entry has the required approvals. This log summary supports the asset-management dashboard. Maintenance notes are archived for compliance audits. Archive this summary in the CMMS for future reference.

Lubrication Checked	N/A
Calibration Verified	Yes
Emergency Stop Tested	N/A

Approved by:	Serviced by: