Check that all downtime events are properly categorized and logged. Refer to the maintenance register for detailed service histories. This log records all maintenance activities performed on the equipment. Ensure all safety checks were completed during servicing. Confirm that service intervals follow the preventive schedule.

## Spare Parts Used:

Part Name	Part No.	Qty Used
Li-Ion Battery Pack	P-9516	5
Li-Ion Battery Pack	P-3393	2
Switch Assembly	P-4361	4

Unit Code	Machine	Service Type	Operator	Duration	Last Check	Site	Comments
MC-275	Lathe	Inspection	Laura Rossi	2.4	2024-07-29		
MC-260	Conveyor Belt	Inspection	Carlos Garcia	2.8	2025-04-18		
MC-220	CNC Milling Machine	Corrective	Carlos Garcia	2.2	2024-11-14	Li-lon battery pack serviced.	
MC-213	Assembly Robot	Corrective	Jan Kowalski	3.4	2025-04-03	Alignment of hinges adjusted.	

Signed off:	Peter Schmidt
Performed by:	Anna Nowak