## **Equipment Record Report**

Performed On: 2024-05-21

Signed off:	Carlos Garcia
Performed by:	Anna Nowak

Refer to the maintenance register for detailed service histories. Confirm that service intervals follow the preventive schedule. Below is the summary of service actions and downtimes for each machine. This service summary supports the reliability engineering review. The equipment log below includes fault codes and corrective notes. Ensure all safety checks were completed during servicing. Use this record to plan upcoming upkeep and repairs.

## Section A:

Unit Code	MC-230	MC-239	MC-205	MC-212	MC-215	MC-245
Equipment	Assembly	CNC Milling	Plasma Cutter	Paint Booth	Lathe	Packaging
	Robot	Machine				Line
Service Type	Preventive	Preventive	Corrective	Corrective	Inspection	Corrective
Operator	Peter Schmidt	Jan Kowalski	Jan Kowalski	Jan Kowalski	Jan Kowalski	Carlos Garcia
Downtime	3.8	1.9	1.7	2.0	2.3	2.2
Comments	Switch contacts	Switch contacts	Replaced coolant.	Changed oil and filters.	Li-lon battery pack serviced.	
	cleaned.	cleaned.				

## Section B:

Unit Code	MC-239	MC-245	MC-297	MC-205	MC-294	MC-230
Equipment	CNC Milling	Packaging	CNC Milling	Plasma Cutter	Plasma Cutter	Assembly
	Machine	Line	Machine			Robot
Service Type	Corrective	Preventive	Preventive	Preventive	Preventive	Inspection
Operator	Anna Nowak	Laura Rossi	Anna Nowak	Carlos Garcia	Jan Kowalski	Carlos Garcia
Downtime	3.5	3.0	3.7	2.7	2.2	2.4
Comments	Wooden pallet	Calibration	Worn gasket		Tightened	Refilled oil
	checked.	check OK.	replaced.		loose bolts.	(HLP 46).

Uptime (%)	Error Count	Notes
92.96%	3	Bolt tightened