Unit Code	Machine	Service Type	Operator	Downtime	Area	Comments
MC-281	Paint Booth	Inspection	Anna Nowak	2.8	Plant 3A	Wooden pallet checked.
MC-286	Conveyor Belt	Corrective	Jan Kowalski	2.2	Plant 3A	Li-Ion battery pack serviced.
MC-297	Hydraulic Press	Preventive	Peter Schmidt	2.2	Plant 3A	Replaced fuse (5A).
MC-295	Laser Cutter	Preventive	Carlos Garcia	2.5	Plant 3A	Sensor recalibrated.
MC-296	Laser Cutter	Inspection	Carlos Garcia	3.8	Plant 3A	Calibration check OK.
MC-255	Assembly Robot	Preventive	Jan Kowalski	1.7	Plant 1C	Replaced coolant.
MC-266	Laser Cutter	Preventive	Carlos Garcia	3.8	Plant 3A	Li-Ion battery pack serviced.
MC-274	Packaging Line	Preventive	Laura Rossi	2.8	Plant 1C	Replaced coolant.
MC-264	Laser Cutter	Preventive	Peter Schmidt	2.8	Plant 1C	Refilled oil (HLP 46).

Use this closure note to update the maintenance KPI tracker. Check remaining life-cycles of key components from this report. Record any spare parts usage for inventory adjustment. This log summary supports the asset-management dashboard. Overall equipment condition is satisfactory post-maintenance.

Lubrication Checked	Yes
Calibration Verified	Yes
Emergency Stop Tested	No

Authorized by	Operator
Authorized by	Operator: