Inspection Results Summary

Supervisor	Laura Rossi
Inspection Date	2025-04-09

This data extract is prepared for quality-control sign-off. Use this results summary to trigger any corrective actions. The inspection register below highlights any out-of-tolerance parts. This summary of measurements supports metrology traceability.

Item Code	PW-515Y	RM-860N	NE-245A	TL-900X	CN-150C
Component	Wooden Pallet	Wooden Pallet	Shaft 500mm	Bearing 6202 ZZ	Steel Sheet A36
Measurement	Inner Diameter	Hole Ø	Height	Inner Diameter	Inner Diameter
Target	95.00	8.51	45.27	9.95	90.39
Observed	95.10	8.62	45.38	10.11	90.46
Delta	+0.10	+0.11	+0.11	+0.16	+0.07
Pass/Fail	V	V	V	V	V

Review failed items against the corrective-action register. Ensure all measuring tools were properly calibrated. Inspection notes have been logged for traceability. Archive this inspection summary for regulatory documentation.

Instrument Calibration Log:

Instrument	Serial No.	Last Calibration Date
Laser Scanner	53533	2025-03-13
Caliper	17252	2024-11-20
Caliper	29613	2025-05-20
Micrometer	23794	2025-03-13