This maintenance extract is prepared for compliance audit trails. Ensure all safety checks were completed during servicing. Refer to the maintenance register for detailed service histories. All technician comments are recorded for maintenance trend analysis.

Spare Parts Used:

Part Name	Part No.	Qty Used
Hinge Set	P-3027	3
Fuse 5A	P-5338	2

Machine ID	Equipment	Туре	Technician	Duration	Previous Service	Area	Notes
MC-234	Hydraulic	Corrective	Peter	1.9	2024-07-17	Tightened	
	Press		Schmidt			loose bolts.	
MC-210	Paint Booth	Inspection	Anna Nowak	3.9	2024-03-28	Replaced	
						fuse (5A).	
MC-283	Lathe	Corrective	Jan Kowalski	3.9	2024-12-24	Switch	
						contacts	
						cleaned.	
MC-223	Hydraulic	Inspection	Anna Nowak	3.0	2023-12-07	Refilled oil	
	Press					(HLP 46).	
MC-217	CNC Milling	Corrective	Laura Rossi	4.0	2024-05-27	Tightened	
	Machine					loose bolts.	
MC-205	Assembly	Inspection	Anna Nowak	3.9	2025-01-09	Switch	
	Robot					contacts	
						cleaned.	
MC-211	CNC Milling	Preventive	Jan Kowalski	3.5	2024-07-25	Alignment of	
	Machine					hinges	
						adjusted.	
MC-227	Laser Cutter	Corrective	Jan Kowalski	3.4	2024-07-27	Changed oil	
						and filters.	
MC-212	Plasma	Inspection	Carlos Garcia	2.5	2023-10-29	Replaced	
	Cutter					coolant.	
MC-241	Hydraulic	Preventive	Peter	3.2	2024-01-01	Sensor	
	Press		Schmidt			recalibrated.	

Signed off:	Laura Rossi
Performed by:	Jan Kowalski