## **Machine Log Summary**

Performed On: 2023-09-12

Signed off:	Peter Schmidt
Performed by:	Carlos Garcia

This service summary supports the reliability engineering review. The following entries detail preventive and corrective maintenance tasks. Confirm that service intervals follow the preventive schedule. Use this record to plan upcoming upkeep and repairs. Use this summary to forecast parts replacement and resource needs. Ensure all safety checks were completed during servicing.

## Section A:

Unit Code	MC-272	MC-222	MC-296	MC-246	MC-234	MC-237
Machine	Laser Cutter	Laser Cutter	Laser Cutter	Hydraulic Press	Lathe	CNC Milling Machine
Туре	Corrective	Inspection	Corrective	Corrective	Inspection	Preventive
Technician	Peter Schmidt	Laura Rossi	Anna Nowak	Jan Kowalski	Jan Kowalski	Carlos Garcia
Duration	3.2	3.6	2.4	3.1	2.3	3.6
Comments	Replaced coolant.	Replaced coolant.	Worn gasket replaced.	Changed oil and filters.	Worn gasket replaced.	Alignment of hinges adjusted.

## Section B:

Unit Code	MC-296	MC-263	MC-272	MC-246	MC-222	MC-238
Machine	Laser Cutter	Plasma Cutter	Laser Cutter	Hydraulic Press	Laser Cutter	Assembly Robot
Туре	Inspection	Preventive	Preventive	Preventive	Inspection	Preventive
Technician	Jan Kowalski	Jan Kowalski	Anna Nowak	Jan Kowalski	Peter Schmidt	Carlos Garcia
Duration	1.6	3.4	3.1	2.4	3.5	3.1
Comments	No issues	Replaced fuse	Switch contacts	Replaced fuse	Wooden pallet	Li-lon battery
	found.	(5A).	cleaned.	(5A).	checked.	pack serviced.

Uptime (%)	Error Count	Notes
93.58%	0	Replaced filter