Use this record to plan upcoming upkeep and repairs. Confirm that service intervals follow the preventive schedule. All technician comments are recorded for maintenance trend analysis. The equipment log below includes fault codes and corrective notes. Refer to the maintenance register for detailed service histories. This log records all maintenance activities performed on the equipment.

Spare Parts Used:

| Part Name | Part No. | Qty Used |
|---------------------|----------|----------|
| Li-Ion Battery Pack | P-8992 | 3 |
| Sealing Gasket | P-5392 | 1 |
| Sealing Gasket | P-8762 | 1 |

| Machine ID | Machine | Service Type | Technician | Downtime | Previous Service | Site | Comments |
|------------|------------------------|--------------|------------------|----------|---------------------|--------------------------|----------|
| MC-238 | Paint Booth | Corrective | Anna Nowak | 1.6 | 2024-12-06 | No issues found. | |
| MC-287 | CNC Milling Machine | Inspection | Peter Schmidt | 1.7 | 2024-11-27 | Tightened loose bolts. | |
| MC-221 | Paint Booth | Inspection | Laura Rossi | 2.7 | 2024-06-30 | Switch contacts cleaned. | |
| MC-250 | Assembly Robot | Inspection | Peter Schmidt | 3.1 | 2024-11-11 | Sensor recalibrated. | |
| MC-269 | CNC Milling Machine | Corrective | Carlos Garcia | 3.2 | 2025-04-06 | Replaced fuse (5A). | |
| MC-203 | Lathe | Corrective | Carlos Garcia | 3.9 | 2025-07-11 | No issues found. | |
| MC-220 | Conveyor Belt | Inspection | Peter Schmidt | 2.6 | 2024-10-05 | Sensor recalibrated. | |
| MC-294 | Plasma Cutter | Inspection | Carlos Garcia | 3.2 | 2024-09-05 | Calibration check OK. | |
| MC-218 | Paint Booth | Corrective | Laura Rossi | 2.6 | 2024-08-02 | Replaced coolant. | |

| Approved by: | Jan Kowalski |
|--------------|--------------|
| Serviced by: | Jan Kowalski |