Machine Log Summary #6818004

Date: 2023-10-06

| Machine ID | Equipment | Туре | Operator | Downtime | Site | Notes |
|------------|---------------|------------|---------------|----------|----------|----------------|
| MC-232 | Plasma Cutter | Corrective | Anna Nowak | 3.4 | Plant 2B | Refilled oil |
| | | | | | | (HLP 46). |
| MC-282 | Conveyor Belt | Corrective | Jan Kowalski | 1.6 | Plant 2B | Wooden pallet |
| | | | | | | checked. |
| MC-209 | Laser Cutter | Inspection | Laura Rossi | 2.9 | Plant 1C | Li-lon battery |
| | | | | | | pack serviced. |
| MC-296 | Lathe | Corrective | Peter Schmidt | 2.8 | Plant 2B | Changed oil |
| | | | | | | and filters. |
| MC-299 | Assembly | Preventive | Jan Kowalski | 2.0 | Plant 2B | Refilled oil |
| | Robot | | | | | (HLP 46). |
| MC-271 | CNC Milling | Inspection | Carlos Garcia | 3.9 | Plant 2B | Alignment of |
| | Machine | | | | | hinges |
| | | | | | | adjusted. |
| MC-216 | Conveyor Belt | Preventive | Jan Kowalski | 3.0 | Plant 2B | Tightened |
| | | | | | | loose bolts. |
| MC-228 | Packaging | Inspection | Laura Rossi | 1.8 | Plant 2B | Li-lon battery |
| | Line | | | | | pack serviced. |
| MC-258 | Conveyor Belt | Inspection | Jan Kowalski | 3.2 | Plant 3A | Calibration |
| | | | | | | check OK. |
| MC-241 | Conveyor Belt | Corrective | Laura Rossi | 2.8 | Plant 3A | Alignment of |
| | | | | | | hinges |
| | | | | | | adjusted. |

Flag any recurring issues for root-cause investigation. Refer to remarks for any follow-up actions or parts replacements. All maintenance tasks have been completed as per schedule. Confirm that all corrective actions were properly closed out. Ensure next preventive service is scheduled according to plan. Check remaining life-cycles of key components from this report.

| Lubrication Checked | Yes |
|-----------------------|-----|
| Calibration Verified | Yes |
| Emergency Stop Tested | No |

| Approved by: | Serviced by: |
|--------------|--------------|
|--------------|--------------|