Unit Code	Machine	Service Type	Operator	Duration	Area	Comments
MC-249	Plasma Cutter	Preventive	Laura Rossi	2.1	Plant 1C	Replaced
						coolant.
MC-245	CNC Milling	Corrective	Carlos Garcia	4.0	Plant 1C	Replaced
	Machine					fuse (5A).
MC-229	Plasma Cutter	Corrective	Carlos Garcia	4.0	Plant 3A	Calibration
						check OK.
MC-247	Paint Booth	Corrective	Jan Kowalski	3.8	Plant 2B	Replaced
						coolant.
MC-250	CNC Milling	Preventive	Jan Kowalski	2.8	Plant 1C	Worn gasket
	Machine					replaced.
MC-214	Lathe	Preventive	Jan Kowalski	2.5	Plant 1C	Wooden
						pallet
						checked.
MC-297	Hydraulic	Preventive	Anna Nowak	1.7	Plant 3A	Alignment of
	Press					hinges
						adjusted.

Flag any recurring issues for root-cause investigation. All maintenance durations are recorded for performance metrics. Ensure that each service entry has the required approvals. No critical faults were found during the latest inspection. This log summary supports the asset-management dashboard.

Lubrication Checked	No
Calibration Verified	No
Emergency Stop Tested	No

Authorized by:	Operator: