Equipment Record Report

Performed On: 2024-05-13

Signed off:	Peter Schmidt
Performed by:	Jan Kowalski

Entries include work orders, technician assignments, and part changes. Ensure all safety checks were completed during servicing. Use this summary to forecast parts replacement and resource needs. Confirm that service intervals follow the preventive schedule. Use this record to plan upcoming upkeep and repairs. Check that all downtime events are properly categorized and logged.

Section A:

Machine ID	MC-250	MC-246	MC-201	MC-216	MC-223	MC-267
Equipment	Lathe	Laser Cutter	Plasma Cutter	Packaging Line	Paint Booth	Conveyor Belt
Type	Preventive	Inspection	Preventive	Corrective	Corrective	Corrective
Technician	Laura Rossi	Peter Schmidt	Anna Nowak	Jan Kowalski	Peter Schmidt	Jan Kowalski
Downtime	3.2	1.7	2.0	2.5	1.7	3.8
Notes	Tightened loose bolts.	Replaced fuse (5A).	Sensor recalibrated.	Tightened loose bolts.	Sensor recalibrated.	Alignment of hinges adjusted.

Section B:

Machine ID	MC-299	MC-280	MC-250	MC-223	MC-297	MC-246
Equipment	CNC Milling	CNC Milling	Lathe	Paint Booth	Conveyor Belt	Laser Cutter
	Machine	Machine			-	
Type	Corrective	Corrective	Preventive	Corrective	Preventive	Corrective
Technician	Anna Nowak	Carlos Garcia	Anna Nowak	Carlos Garcia	Carlos Garcia	Carlos Garcia
Downtime	2.6	2.0	3.0	3.6	3.6	2.1
Notes	Worn gasket replaced.	No issues found.	Refilled oil (HLP 46).	Refilled oil (HLP 46).	Alignment of hinges adjusted.	Refilled oil (HLP 46).

Uptime (%)	Error Count	Comments
92.61%	5	Replaced filter