## Maintenance Checklist Report #7612562

Date: 2023-09-09

Machine ID	Equipment	Туре	Operator	Duration	Site	Comments
MC-207	Plasma Cutter	Preventive	Carlos Garcia	2.0	Plant 1C	Replaced
						coolant.
MC-248	Assembly	Corrective	Jan Kowalski	3.4	Plant 1C	Changed oil
	Robot					and filters.
MC-251	CNC Milling	Corrective	Laura Rossi	2.5	Plant 2B	No issues
	Machine					found.
MC-246	Hydraulic	Preventive	Anna Nowak	2.1	Plant 1C	Li-lon battery
	Press					pack serviced.
MC-281	Plasma Cutter	Corrective	Peter Schmidt	1.7	Plant 1C	Changed oil
						and filters.
MC-254	CNC Milling	Corrective	Carlos Garcia	3.9	Plant 2B	Alignment of
	Machine					hinges
						adjusted.
MC-210	Laser Cutter	Corrective	Laura Rossi	2.2	Plant 1C	Wooden pallet
						checked.
MC-253	Assembly	Inspection	Jan Kowalski	2.9	Plant 1C	Tightened
	Robot					loose bolts.

Overall equipment condition is satisfactory post-maintenance. Service summaries have been forwarded to the engineering team. No critical faults were found during the latest inspection. This log summary supports the asset-management dashboard.

Lubrication Checked	Yes
Calibration Verified	N/A
Emergency Stop Tested	No

Signed off.	Performed by: