Machine Log Summary

Performed On: 2025-05-14

Approved by:	Laura Rossi
Serviced by:	Peter Schmidt

Use this summary to forecast parts replacement and resource needs. The equipment log below includes fault codes and corrective notes. Confirm that service intervals follow the preventive schedule. Check that all downtime events are properly categorized and logged. This service summary supports the reliability engineering review. This maintenance extract is prepared for compliance audit trails.

Section A:

Machine ID	MC-259	MC-256	MC-227	MC-242	MC-260	MC-214
Machine	Paint Booth	Packaging	Hydraulic	Laser Cutter	Packaging	Laser Cutter
		Line	Press		Line	
Service Type	Preventive	Preventive	Preventive	Corrective	Inspection	Preventive
Technician	Laura Rossi	Carlos Garcia	Peter Schmidt	Peter Schmidt	Anna Nowak	Peter Schmidt
Duration	3.0	3.2	3.1	2.3	3.2	3.0
Comments	Sensor	Calibration	Calibration		Li-lon battery	Li-lon battery
	recalibrated.	check OK.	check OK.		pack serviced.	pack serviced.

Section B:

Machine ID	MC-227	MC-214	MC-287	MC-277	MC-259	MC-260
Machine	Hydraulic	Laser Cutter	Conveyor Belt	Hydraulic	Paint Booth	Packaging
	Press			Press		Line
Service Type	Preventive	Preventive	Inspection	Preventive	Preventive	Inspection
Technician	Laura Rossi	Anna Nowak	Carlos Garcia	Peter Schmidt	Carlos Garcia	Jan Kowalski
Duration	3.8	3.3	1.7	1.6	3.9	3.3
Comments	Changed oil	Replaced	Replaced fuse	Replaced fuse	Changed oil	Tightened
	and filters.	coolant.	(5A).	(5A).	and filters.	loose bolts.

Confirm that all corrective actions were properly closed out. All maintenance tasks have been completed as per schedule. This log summary supports the asset-management dashboard.

Uptime (%)	Error Count	Comments
98.87%	1	Bolt tightened