## **Inspection Record**

This checklist captures quality inspection points and sampling levels. Entries include both visual and functional inspection items. This section details quality requirements and test points for the batch. All checklist entries are timestamped for traceability. This summary supports the production-release quality gate. Ensure all non-conforming marks are clearly documented. Please review each checklist point and mark the sampling results. Check that inspection steps follow the approved procedure.

Product ID	CN-150C	Customer ID	GREECE
Item Description	Fuse 5A		

	Quality Check Items	Sampling Level	Severity				Comments
Z	Product Requirements		С	M	m	Н	
1	Dead or live insect in packaging	Level III			٧	٧	Critical impact
2	Color mismatch	Level II		V	V		Minor issue observed
3	Rubber Switch not working	Level III	V		V		Minor issue observed
4	Wood splinter or sharp point on product	Level III	V				
5	Screws loose or missing	Level III	V	V			Needs review
6	Package is not sealed completely			V			Needs review
7	Packaging does not match signed sample	Level III	V			V	Critical impact

Supervised by	<i>r</i> :	Date: