Machine ID	Machine	Service Type	Operator	Downtime	Site	Comments
MC-270	Paint Booth	Preventive	Carlos Garcia	3.7	Plant 2B	No issues
						found.
MC-271	Packaging	Inspection	Carlos Garcia	3.8	Plant 2B	Refilled oil
	Line					(HLP 46).
MC-262	Packaging	Inspection	Peter Schmidt	2.8	Plant 3A	Replaced fuse
	Line					(5A).
MC-258	Laser Cutter	Preventive	Peter Schmidt	4.0	Plant 2B	Replaced
						coolant.
MC-260	Conveyor Belt	Inspection	Peter Schmidt	3.2	Plant 2B	Changed oil
						and filters.
MC-245	Conveyor Belt	Corrective	Anna Nowak	2.8	Plant 2B	Tightened
						loose bolts.

Refer to remarks for any follow-up actions or parts replacements. All maintenance tasks have been completed as per schedule. Ensure next preventive service is scheduled according to plan. Flag any recurring issues for root-cause investigation.

Lubrication Checked	No
Calibration Verified	No
Emergency Stop Tested	N/A

Approved by:	Serviced by:
.pp.o.ca by	Corviced by: