## **Equipment Record Report #2032441**

Date: 2024-05-18

Machine ID	Machine	Service Type	Technician	Duration	Area	Notes
MC-299	Hydraulic	Corrective	Anna Nowak	3.6	Plant 2B	Wooden pallet
	Press					checked.
MC-237	Assembly	Preventive	Anna Nowak	3.8	Plant 3A	Tightened
	Robot					loose bolts.
MC-202	Plasma Cutter	Corrective	Anna Nowak	2.1	Plant 1C	Replaced
						coolant.
MC-221	Assembly	Inspection	Laura Rossi	1.9	Plant 3A	Refilled oil
	Robot					(HLP 46).
MC-262	Lathe	Corrective	Anna Nowak	2.3	Plant 2B	Replaced fuse
						(5A).
MC-284	Conveyor Belt	Preventive	Carlos Garcia	3.5	Plant 3A	Worn gasket
						replaced.
MC-270	Laser Cutter	Corrective	Laura Rossi	1.9	Plant 1C	Calibration
						check OK.
MC-282	Conveyor Belt	Corrective	Peter Schmidt	2.9	Plant 3A	
MC-235	Lathe	Preventive	Jan Kowalski	1.8	Plant 2B	Refilled oil
						(HLP 46).

Archive this summary in the CMMS for future reference. Ensure next preventive service is scheduled according to plan. Overall equipment condition is satisfactory post-maintenance. Use this closure note to update the maintenance KPI tracker.

Lubrication Checked	N/A		
Calibration Verified	N/A		
Emergency Stop Tested	N/A		

Approved by:	Serviced by:
--------------	--------------