Maintenance Checklist Report #7882630

Date: 2024-09-29

| Machine ID | Equipment | Service Type | Operator | Downtime | Site | Notes |
|------------|------------------------|--------------|---------------|----------|----------|-------------------------------|
| MC-296 | Hydraulic Press | Preventive | Anna Nowak | 3.5 | Plant 3A | No issues found. |
| MC-282 | CNC Milling Machine | Preventive | Jan Kowalski | 3.0 | Plant 1C | |
| MC-212 | CNC Milling Machine | Preventive | Peter Schmidt | 1.8 | Plant 1C | Replaced coolant. |
| MC-260 | Hydraulic Press | Corrective | Peter Schmidt | 2.1 | Plant 2B | Li-lon battery pack serviced. |
| MC-236 | Lathe | Inspection | Jan Kowalski | 3.7 | Plant 3A | Switch contacts cleaned. |
| MC-235 | CNC Milling Machine | Preventive | Peter Schmidt | 3.1 | Plant 2B | No issues found. |
| MC-217 | CNC Milling Machine | Inspection | Peter Schmidt | 3.5 | Plant 1C | Sensor recalibrated. |
| MC-240 | Lathe | Preventive | Anna Nowak | 3.5 | Plant 2B | Alignment of hinges adjusted. |
| MC-267 | Paint Booth | Corrective | Laura Rossi | 1.6 | Plant 2B | Switch contacts cleaned. |
| MC-224 | Plasma Cutter | Preventive | Carlos Garcia | 2.4 | Plant 1C | Tightened loose bolts. |

Overall equipment condition is satisfactory post-maintenance. Archive this summary in the CMMS for future reference. All maintenance tasks have been completed as per schedule. This log summary supports the asset-management dashboard.

| Lubrication Checked | N/A |
|-----------------------|-----|
| Calibration Verified | N/A |
| Emergency Stop Tested | Yes |

| Signed off: | Performed by: |
|-------------|---------------|