Machine Log Summary #4719485

Date: 2025-02-07

Machine ID	Equipment	Туре	Operator	Duration	Area	Comments
MC-267	Conveyor Belt	Corrective	Laura Rossi	4.0	Plant 1C	Calibration check OK.
MC-231	Laser Cutter	Preventive	Anna Nowak	2.1	Plant 2B	Li-lon battery pack serviced.
MC-286	Packaging Line	Corrective	Anna Nowak	3.3	Plant 1C	Replaced fuse (5A).
MC-207	Assembly Robot	Corrective	Carlos Garcia	4.0	Plant 3A	Calibration check OK.
MC-244	Hydraulic Press	Preventive	Peter Schmidt	2.0	Plant 1C	Worn gasket replaced.
MC-285	Assembly Robot	Preventive	Carlos Garcia	1.9	Plant 1C	Tightened loose bolts.
MC-232	Lathe	Preventive	Anna Nowak	3.8	Plant 2B	Alignment of hinges adjusted.
MC-217	CNC Milling Machine	Corrective	Peter Schmidt	2.5	Plant 2B	Switch contacts cleaned.
MC-241	Assembly Robot	Corrective	Peter Schmidt	2.5	Plant 3A	No issues found.
MC-203	Conveyor Belt	Preventive	Anna Nowak	3.0	Plant 2B	Replaced coolant.

No critical faults were found during the latest inspection. All maintenance tasks have been completed as per schedule. Ensure that each service entry has the required approvals. Service summaries have been forwarded to the engineering team. Refer to remarks for any follow-up actions or parts replacements.

Lubrication Checked	N/A
Calibration Verified	No
Emergency Stop Tested	No