Machine ID	Machine	Service Type	Technician	Downtime	Site	Comments
MC-232	Plasma Cutter	Preventive	Jan Kowalski	2.6	Plant 1C	Calibration
						check OK.
MC-288	Assembly	Inspection	Laura Rossi	3.7	Plant 3A	Wooden pallet
	Robot					checked.
MC-248	Plasma Cutter	Preventive	Laura Rossi	3.7	Plant 3A	Replaced
						coolant.
MC-206	Plasma Cutter	Preventive	Laura Rossi	3.8	Plant 2B	Calibration
						check OK.
MC-252	Paint Booth	Inspection	Jan Kowalski	2.2	Plant 2B	Switch contacts
						cleaned.
MC-290	Laser Cutter	Inspection	Carlos Garcia	2.1	Plant 2B	Tightened
						loose bolts.
MC-218	Conveyor Belt	Inspection	Carlos Garcia	2.7	Plant 2B	Changed oil
						and filters.
MC-255	Plasma Cutter	Inspection	Laura Rossi	3.5	Plant 2B	Alignment of
						hinges
						adjusted.

No critical faults were found during the latest inspection. Maintenance notes are archived for compliance audits. Record any spare parts usage for inventory adjustment. Flag any recurring issues for root-cause investigation. Ensure next preventive service is scheduled according to plan. This log summary supports the asset-management dashboard.

Lubrication Checked	Yes
Calibration Verified	Yes
Emergency Stop Tested	N/A

Signed off:	Performed by: