Machine Log Summary #5676880

Date: 2024-06-23

Unit Code	Equipment	Туре	Technician	Downtime	Site	Comments
MC-282	Hydraulic Press	Preventive	Carlos Garcia	2.5	Plant 3A	Switch contacts cleaned.
MC-276	Assembly Robot	Inspection	Peter Schmidt	1.9	Plant 1C	
MC-290	Packaging Line	Inspection	Jan Kowalski	1.8	Plant 2B	Li-lon battery pack serviced.
MC-208	Lathe	Preventive	Laura Rossi	2.2	Plant 2B	Replaced coolant.
MC-210	Assembly Robot	Inspection	Carlos Garcia	2.4	Plant 1C	Refilled oil (HLP 46).
MC-242	CNC Milling Machine	Corrective	Peter Schmidt	2.7	Plant 3A	Alignment of hinges adjusted.
MC-269	CNC Milling Machine	Inspection	Peter Schmidt	2.5	Plant 3A	Wooden pallet checked.
MC-296	Assembly Robot	Corrective	Jan Kowalski	2.0	Plant 1C	Li-lon battery pack serviced.
MC-224	Packaging Line	Inspection	Laura Rossi	2.8	Plant 1C	Replaced coolant.
MC-299	Hydraulic Press	Inspection	Laura Rossi	3.6	Plant 1C	Tightened loose bolts.

This log summary supports the asset-management dashboard. Record any spare parts usage for inventory adjustment. Flag any recurring issues for root-cause investigation. Confirm that all corrective actions were properly closed out. No critical faults were found during the latest inspection. Maintenance notes are archived for compliance audits.

Lubrication Checked	No
Calibration Verified	Yes
Emergency Stop Tested	N/A

Authorized by:	Operator:	