

Production Log

Report No.: PR-992

Customer: BRAZIL

Shift: B (Evening)

Date: 06-06-2024

Machine	Task	Operator	Start Time	To	Time Spent	Remarks	Stage
MC-201	Cutting	Anna Nowak	09:00	10:21	81	OK	In progress
MC-206	Assembly	Wiktor Kopczyński	07:30	08:01	31		In progress
MC-203	Polishing	Agnieszka Zielińska	12:00	12:57	57	Recalibrated	Completed
MC-201	Cutting	Nadia Sauter	08:00	08:36	36		Completed
MC-203	Welding	Jan Kowalski	06:30	07:12	42		Delayed
MC-202	Polishing	Bartosz Wawrzyniak	06:00	07:15	75		In progress
MC-204	Polishing	Bartosz Wawrzyniak	06:00	07:44	104		In progress
MC-204	Cutting	Jan Kowalski	12:00	13:20	80	OK	Delayed
MC-201	Polishing	Przemysław Wąsik	12:15	14:05	110		Delayed
MC-202	Assembly	Jan Kowalski	13:00	13:56	56	Recalibrated	In progress
MC-203	Polishing	Wiktor Kopczyński	12:00	13:52	112	N/A	Delayed

Ensure routine maintenance between shifts to maintain consistent output. Refer to remarks for any rework or quality concerns. Check material consumption against standard usage rates. No critical delays were observed; please address any minor issues noted. Archive this output summary for end-of-day reporting. This closure summary signals readiness for the next production run.

Item ID	Planned Output	Produced Qty	Rejected Qty	Scrap %	Rework Count	Remarks
JD-700W	197	178	19	9.64%	5	Rework needed
XK-610U	206	200	6	2.91%	0	
LK-890B	278	241	37	13.31%	9	Rework needed

Approved by: _____ Prepared by: _____