

Machine Log Summary #5208773

Date: 2024-11-16

Machine ID	Equipment	Service Type	Operator	Duration	Site	Comments
MC-243	Paint Booth	Preventive	Laura Rossi	1.8	Plant 1C	Replaced coolant.
MC-203	Laser Cutter	Preventive	Carlos Garcia	2.3	Plant 2B	Replaced coolant.
MC-240	Assembly Robot	Preventive	Laura Rossi	3.2	Plant 3A	
MC-283	Lathe	Corrective	Laura Rossi	3.4	Plant 2B	Alignment of hinges adjusted.
MC-291	Paint Booth	Preventive	Laura Rossi	2.9	Plant 3A	Alignment of hinges adjusted.
MC-262	Paint Booth	Preventive	Anna Nowak	2.5	Plant 1C	
MC-228	CNC Milling Machine	Preventive	Carlos Garcia	2.0	Plant 2B	Replaced coolant.
MC-266	Packaging Line	Preventive	Laura Rossi	2.9	Plant 2B	Worn gasket replaced.

No critical faults were found during the latest inspection. Flag any recurring issues for root-cause investigation. Use this closure note to update the maintenance KPI tracker. Overall equipment condition is satisfactory post-maintenance.

Lubrication Checked	No
Calibration Verified	Yes
Emergency Stop Tested	N/A

Approved by: _____ Serviced by: _____