

Confirm that service intervals follow the preventive schedule. Below is the summary of service actions and downtimes for each machine. Ensure all safety checks were completed during servicing. This maintenance extract is prepared for compliance audit trails. Use this record to plan upcoming upkeep and repairs. This service summary supports the reliability engineering review.

Spare Parts Used:

| Part Name           | Part No. | Qty Used |
|---------------------|----------|----------|
| Sealing Gasket      | P-3178   | 5        |
| Li-Ion Battery Pack | P-9470   | 5        |
| Hinge Set           | P-1093   | 4        |

| Machine ID | Machine             | Type       | Operator      | Duration | Last Check | Site                          | Comments |
|------------|---------------------|------------|---------------|----------|------------|-------------------------------|----------|
| MC-288     | Packaging Line      | Corrective | Carlos Garcia | 2.6      | 2024-11-05 | Changed oil and filters.      |          |
| MC-260     | Laser Cutter        | Inspection | Peter Schmidt | 2.0      | 2025-07-03 | Tightened loose bolts.        |          |
| MC-265     | Hydraulic Press     | Corrective | Jan Kowalski  | 3.2      | 2024-01-22 | Replaced fuse (5A).           |          |
| MC-271     | Lathe               | Preventive | Jan Kowalski  | 1.5      | 2025-04-21 | Calibration check OK.         |          |
| MC-289     | Paint Booth         | Inspection | Jan Kowalski  | 3.1      | 2024-02-10 | Replaced coolant.             |          |
| MC-208     | Paint Booth         | Inspection | Laura Rossi   | 3.5      | 2024-12-23 | Changed oil and filters.      |          |
| MC-214     | Laser Cutter        | Preventive | Jan Kowalski  | 2.0      | 2024-05-29 | Switch contacts cleaned.      |          |
| MC-229     | CNC Milling Machine | Preventive | Peter Schmidt | 2.7      | 2024-08-21 | Alignment of hinges adjusted. |          |
| MC-277     | Hydraulic Press     | Corrective | Jan Kowalski  | 2.9      | 2024-04-11 | Replaced fuse (5A).           |          |
| MC-246     | Conveyor Belt       | Corrective | Carlos Garcia | 2.2      | 2024-01-31 | Calibration check OK.         |          |

|                |               |
|----------------|---------------|
| Authorized by: | Peter Schmidt |
| Operator:      | Carlos Garcia |