

Equipment Record Report

Performed On: 2025-07-12

Approved by:	Peter Schmidt
Serviced by:	Carlos Garcia

Check that all downtime events are properly categorized and logged. Confirm that service intervals follow the preventive schedule. Use this record to plan upcoming upkeep and repairs. Refer to the maintenance register for detailed service histories. The equipment log below includes fault codes and corrective notes.

Section A:

Unit Code	MC-296	MC-270	MC-201	MC-265	MC-239	MC-273
Machine	Paint Booth	Assembly Robot	Paint Booth	Hydraulic Press	Packaging Line	Laser Cutter
Type	Inspection	Corrective	Preventive	Inspection	Corrective	Inspection
Technician	Laura Rossi	Jan Kowalski	Peter Schmidt	Jan Kowalski	Jan Kowalski	Peter Schmidt
Duration	3.8	3.2	1.7	2.6	3.5	2.1
Notes	Li-Ion battery pack serviced.	Wooden pallet checked.	Switch contacts cleaned.	Li-Ion battery pack serviced.		Sensor recalibrated.

Section B:

Unit Code	MC-247	MC-265	MC-262	MC-270	MC-224	MC-239
Machine	Packaging Line	Hydraulic Press	CNC Milling Machine	Assembly Robot	Assembly Robot	Packaging Line
Type	Preventive	Corrective	Preventive	Preventive	Preventive	Corrective
Technician	Jan Kowalski	Laura Rossi	Carlos Garcia	Peter Schmidt	Peter Schmidt	Anna Nowak
Duration	1.6	3.6	3.1	2.5	3.1	2.6
Notes	Replaced coolant.	Worn gasket replaced.	Refilled oil (HLP 46).	Changed oil and filters.	Worn gasket replaced.	Calibration check OK.

Uptime (%)	Error Count	Comments
97.93%	0	