

Inspection Record

#8554297

Date: 26.08.2025

Product ID	DX-777T	Customer ID	BRAZIL
Item Description	Rubber Gasket 80mm		

Entries include both visual and functional inspection items. Please review each checklist point and mark the sampling results. This summary supports the production-release quality gate. This section details quality requirements and test points for the batch. All checklist entries are timestamped for traceability. Use this list to confirm adherence to AQL and safety standards. Check that inspection steps follow the approved procedure. Below are the items to be verified during the final product review.

	Inspection Checklist Points	Sample Tier	Defect Class				Remarks
			Critical	Major	Minor	OnHold	
X	Component Criteria						
1	Packaging does not match signed sample	Level I			V	V	Needs review
2	Color mismatch						
3	Not assembled as per drawing	Level II	V		V		Needs review
4	Hinges loose	Level II			V	V	Needs review
5	Missing distributor information	Level I	V			V	Minor issue observed
6	Incorrect quantity or assortment		V		V		Needs review
7	Rubber Switch not working	Level III		V	V		Minor issue observed
8	Screws loose or missing	Level III		V			Needs review
9	Loose parts inside packaging	Level I					
10	Carton is damaged or markings incorrect	Level II		V	V		Minor issue observed
11	Incorrect orientation in box				V		Minor issue observed
12	Visual defect on housing						Critical impact
13	Wrong product size	Level II			V		Minor issue observed
14	Sharp edges on plastic components	Level II				V	Needs review
15	Dust/debris inside packaging						Needs review

AQL Level	Critical	Major	Minor
Default	0	2.5	4.0
Customer specific			V

Checklist results have been reported to the quality manager. Please ensure supervised sign-off on any non-conforming points. Use this closure report to update the quality KPI dashboard. Overall quality status indicates compliance with defined AQL levels. Corrective actions are scheduled for identified issues. Confirm that all sampling results are within acceptable limits. All critical and major inspection points have been addressed.