

(02) 796 5092 *J* rakkiiautoservices@yahoo.com **M** 71 Santol St.Niño, Quezon City, 1113 *©*

	REPAIR JOB ESTIMATE			
Customer:	Janrey A. Cablinda		Date:	2021-12-05
Address:	San juan 2 lapasan CDO			
Insurance:	PHIL. BRITISH			
Vehicle:	VIOS		PLATE NO.:	KVN999
	SCOPE OF WORK		LABOR	LABOR
I - PARTS TO BE REPAIR			₽0	₽0
FRT BUMBER COVER			₱2000	₱2000
BUMBER CLIPS			₱1000	₱1000
II - PULLDOWN ALL NEC. PARTS TO GIVEWAY FOR REPAIR			₱200	₱200
test			₱100	₱100
		SUB-TOTAL	2 3300	₱3300
12% V			:₱396	
TOTAL LABOR AND PARTS ₱6996			FRED MORAN	
The above ESTIMATE is based on our inspection and does not cover/include broken or additional labor which are not evident on the first inspection. Qoutation and parts/labor are current and subject to change notice. This estimate is only good for fifteen days, and is NOT VALID FOR COURT PURPOSES. RAKKII AUTO SERVICE shall not be liable for loss/es or any damage/s to vehicle or any			APPROVED BY REZZA LYNN BITENG GENERAL MANAGER	