

(02) 796 5092 *J* rakkiiautoservices@yahoo.com **M** 71 Santol St.Niño, Quezon City, 1113 *©*

	REPAIR JOB ESTIMATE			
Customer:	Christine Del	Date:	2021-12-04	
Address:	San juan			
Insurance:	PHIL. BRITISH			
Vehicle:	NAVARA	PLATE NO.:	LDN925	
SCOPE OF WORK			LABOR	
I - PARTS TO BE REPAIR			₽0	
BUMBER CLIPS			₱400	
II - PULLDOWN ALL NEC. PARTS TO GIVEWAY FOR REPAIR			₱100	
	SUB-TOTAL	₱400	₱500	
	12% VAT	1 948		
TOTAL LABOR AND PARTS ₱948			FRED MORAN	
The above ESTIMATE is based on our inspection and does not cover/include broken or additional labor which are not evident on the first inspection. Qoutation and parts/labor are current and subject to change notice. This estimate is only good for fifteen days, and is NOT VALID FOR COURT PURPOSES. RAKKII AUTO SERVICE shall not be liable for loss/es or any damage/s to vehicle or any			APPROVED BY REZZA LYNN BITENG GENERAL MANAGER	