

(02) 796 5092 *J* rakkiiautoservices@yahoo.com **M** 71 Santol St.Niño, Quezon City, 1113 *©*

	REPAIR JOB ESTIMATE			
Customer:	Shiela Mae Gamos	D	Pate:	2021-12-02
Address:	test			
Insurance:	PHIL. BRITISH			
Vehicle:	VIOS	Р	PLATE NO.:	CGY9636
SCOPE OF WORK			LABOR	LABOR
I - PARTS TO BE REPAIR			₽0	₽0
FRT BUMBER COVER			₱100	₱100
BUMBER CLIPS			₱200	₱200
II - PULLDOWN ALL NEC. PARTS TO GIVEWAY FOR REPAIR			₽0	₽0
test			₱2000	₱2000
	SU	B-TOTAL: ₱	2300	₱2300
		12% VAT: ₱	276	
TOTAL LABOR AND PARTS ₱4876			FRED MORAN	
The above ESTIMATE is based on our inspection and does not cover/include broken or additional labor which are not evident on the first inspection. Qoutation and parts/labor are current and subject to change notice. This estimate is only good for fifteen days, and is NOT VALID FOR COURT PURPOSES. RAKKII AUTO SERVICE shall not be liable for loss/es or any damage/s to vehicle or any		oor are is NOT	APPROVED BY REZZA LYNN BITENG GENERAL MANAGER	