

(02) 796 5092 *J* rakkiiautoservices@yahoo.com **M** 71 Santol St.Niño, Quezon City, 1113 *©* 

	REPAIR JOB ESTIMATE			
Customer:	Janrey A. Cablinda	Date:	2021-12-01	
Address:	San juan 2 lapasan CDO			
Insurance:	PHIL. BRITISH			
Vehicle:	VIOS	PLATE NO.:	KVN999	
SCOPE OF WORK			LABOR	
I - PARTS TO BE REPAIR		₽0	₱0	
FRT BUMBER COVER			₱200	
BUMBER CLIPS		₱100	₱200	
	SUB-TOTAL:	₱200	₱400	
	12% VAT:	₱24		
TOTAL LABOR AND PARTS ₱624			FRED MORAN	
The above ESTIMATE is based on our inspection and does not cover/include broken or additional labor which are not evident on the first inspection. Qoutation and parts/labor are current and subject to change notice. This estimate is only good for fifteen days, and is NOT VALID FOR COURT PURPOSES. RAKKII AUTO SERVICE shall not be liable for loss/es or any damage/s to vehicle or any		APPROVED BY REZZA LYNN BITENG GENERAL MANAGER		