

Required PPE:



Step	Image	Description	Hazard(s)	Original Severity	Original Probability	Original Risk	Control(s)	Mitigated Severity	Mitigated Probability	Mitigated Risk
1		Ensure All Wheel Valves are Open	ergonomics, bending, pushing, pulling, squatting, slips, trips.	Serious Injury (Loss)	Reasonably Likely	High	Eng- valves on TPC, wheel chocks. Admin- follow S.O.P procedure to ensure properly done, watch your footing, proper ergonomics PPE- CSA approved FR coveralls, hard hat, boots, gloves and safety glasses, hearing protection.	Negligible (First Aid)	Unlikely	Low
2		Monitor for Leaks	ergonomics, strains, bending, slips, trips	Serious Injury (Loss)	Reasonably Likely	High	Eng- Gauges, Digital box, Windex. Admin- Follow S.O.P procedure to ensure done properly, monitor gauges and digital box. PPE- CSA approved FR coveralls, boots, hard hat, gloves, eye glasses and hearing protection.	Negligible (First Aid)	Unlikely	Low
3		TPC Operations	Exhausting Air, Lack of Knowledge, Slips, Trips, Falls, Dust, Ergonomics.	Serious Injury (Loss)	Reasonably Likely	High	Eng- Gauges, Digital Box, TPC Instructional Video. Admin- Follow S.O.P Procedure, Wear PPE, Ask Supervisor if in Doubt. PPE- CSA Approved FR Coveralls, Boots, Hard Hat, Gloves, Safety Glasses and Hearing Protection.	Negligible (First Aid)	Unlikely	Low