

Required PPE:



Step	Image	Description	Hazard(s)	Original Severity	Original Probability	Original Risk	Control(s)	Mitigated Severity	Mitigated Probability	Mitigated Risk
1		Greasing	Lifting, Twisting Bending, Stretching	Serious Injury (Loss)	Highly Probable	Critical	Eng - Correct Grease Gun for the Job. Correct Grease for Season Admin - Shut Off Equipment, Lock Out Procedure, Follow Procedure. Make Time to do Job Properly PPE - Proper CSA Foot Wear, F/R Outerwear, CSA Safety Glasses, Hardhat, Gloves, Hearing Protection	Negligible (First Aid)	Unlikely	Low
2		Oil Change	Lifting, Twisting Bending, Stretching, Hot Oil. Cold Ground	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Shut Off Equipment, Lock Out Procedure, Follow Procedure. Make Time to do Job Properly PPE - Proper CSA Foot Wear, F/R Outerwear, CSA Safety Glasses, Hardhat, Gloves, Hearing Protection	Negligible (First Aid)	Unlikely	Low
3		Diff Oil Check	Lifting, Twisting Bending, Stretching, Hot Oil. Cold Ground	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Shut Off Equipment, Lock Out Procedure, Follow Procedure. Make Time to do Job Properly PPE - Proper CSA Foot Wear, F/R Outerwear, CSA Safety Glasses, Hardhat, Gloves, Hearing Protection	Negligible (First Aid)	Unlikely	Low

4		Transmission Oil Check	Lifting, Twisting Bending, Stretching, Hot Oil. Cold Ground	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Shut Off Equipment, Lock Out Procedure, Follow Procedure. Make Time to do Job Properly PPE - FR Coveralls, Hardhat, Gloves, Eye Glasses, Steel Toed Boots, Hearing Protection	Negligible (First Aid)	Unlikely	Low
5		Oil Filter Change	Lifting, Twisting Bending, Stretching, Hot Oil. Cold Ground	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Shut Off Equipment, Lock Out Procedure, Follow Procedure. Make Time to do Job Properly PPE - FR Coveralls, Hardhat, Gloves, Eye Glasses, Steel Toed Boots, Hearing Protection	Negligible (First Aid)	Unlikely	Low
6		Air Filter Change	Lifting, Twisting, Bending, Stretching, Slips and Falls	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Shut Off Equipment, Lock Out Procedure, Follow Procedure. Make Time to do Job Properly PPE - FR Coveralls, Hardhat, Gloves, Eye Glasses, Steel Toed Boots, Hearing Protection	Negligible (First Aid)	Unlikely	Low
7		Hibon Oil Change	Lifting, Twisting Bending, Stretching, Hot Oil. Cold Ground	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Shut Off Equipment, Lock Out Procedure, Follow Procedure. Make Time to do Job Properly PPE - FR Coveralls, Hardhat, Gloves, Eye Glasses, Steel Toed Boots, Hearing Protection	Negligible (First Aid)	Unlikely	Low
8		Check Coolant	Lifting, Twisting, Bending, Stretching, Slips and Falls. Hot Liquids Splashing	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Shut Off Equipment, Lock Out Procedure, Follow Procedure. Make Time to do Job Properly. Take care PPE - FR Coveralls, Hardhat, Gloves, Eye Glasses, Steel Toed Boots, Hearing Protection	Negligible (First Aid)	Unlikely	Low

