

Required PPE:



Step	Image	Description	Hazard(s)	Original Severity	Original Probability	Original Risk	Control(s)	Mitigated Severity	Mitigated Probability	Mitigated Risk
1		Fueling Locations	Open Pits, Cattle and Gates, Other Drivers, Pinch Points	Serious Injury (Loss)	Highly Probable	Critical	Eng - Maps, Directions Admin - Stay Away From Pits, Close Gates, Be Aware of Other Drivers PPE - CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection	Negligible (First Aid)	Unlikely	Low
2		Communication	Run Out of Fuel, Rig Has to Wait, Spills	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Have Good Communication, Let Someone Know Where You are Going. PPE - CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection	Negligible (First Aid)	Unlikely	Low
3		Oportunities	Run Out of Fuel, Rig Has to Wait, Spills, Late For Job	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Fuel up Everyday, Plan Ahead, Talk to Your Cross Shift. PPE - CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection	Negligible (First Aid)	Unlikely	Low
4		Record Amount	Noncompliant Log Book, Ticket,	Serious Injury (Loss)	Highly Probable	Critical	Eng - Log Book, Pre/Post Admin - Gaurds Against Theft, Keeps DOT Happy, Part of Your Daily Log PPE -CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection	Negligible (First Aid)	Unlikely	Low

