



3.02 Switching Out Operators

1. Purpose

The purpose of the Standard Operating Procedure is to identify the hazards, implement the proper controls to reduce or eliminate the hazards and define the steps in switching out operators on shallow gas projects and long-term wells.

2. Scope

This procedure is intended for use by all Silverpoint Employees.

3. Hazard Identification

- Physical Stress.
- Personal Injury.
- Pinch Points.
- Driving.
- Weather.
- Slips, Trips and Falls.
- Environmental Release.

4. EHS Requirements

- Fire Retardant Coveralls.
- Steel Toed Boots (ankle support)
- Safety Glasses.
- Gloves.
- Hard Hat.
- Hearing Protection.
- Seat Belts.
- Obey Speed Limits.
- Drive According to Road Conditions.
- Tire Chains.
- Keep Eyes on the Task and Pay Attention.



- Chock Blocks .
- Lock Out Safety Devices .
- Maps .

5. References

- Silverpoint Corporate Codes of Practice
- Alberta OH&S
- Silverpoint Task List
- Silverpoint THA 3.02

6. Procedure for Single Operator Projects

- 6.1. Arrive early at the worksite so that you can become familiar with what needs to be completed .
- 6.2. If possible , introduce relief operator to the consultant and familiarize him with worksite .
- 6.3. Show relief operator where fuel site is, or tell him the arrangements on fueling opportunities .
- 6.4. Review field ticket and discuss how the consultant wants the tickets done .
- 6.5. Travel to the spread field/water source and show them where the last spread was and drive spread field for hazards .
Record any hazards on the safety meeting . **Failure to properly show the incoming operator the spread field/water source can result in spreading in the wrong area, spreading to close to a water body or double spreading or pulling water from wrong source .**
- 6.6. Travel to the cement pit and shale pit to inspect them for hazards . (Refer to SOP 5.02, Working with open pits) record on safety meeting .
- 6.7. Review the well site trailer PMI and record any personal belongings that you are leaving in the trailer on the well site trailer PMI .
- 6.8. Review the vacuum /water truck PMI and complete an inventory checklist , record any missing items or damaged equipment , both operators need to sign off on reviewed PMI .
- 6.9. Review a pre job safety meeting and hazard assessment with the incoming operator listing any hazards that were found as well as the controls put in place and post it in the well site trailer , be sure both operators sign the safety meeting .
- 6.10. Both operators need to sign and date the truck PMI , trailer PMI and safety meetings .
- 6.11. When you are relieving an operator for days off feel free to clean and tidy up equipment but please leave tools and equipment in the same places as the original operator keeps them .

7. 2 Operator Projects



- 7.1. If you are on a 2-driver project , make note of the time you relieve the driver . This is the time that that driver will relieve you. E.g., If you relieve the driver at 7pm they will be back to relieve you at 7am . Arrive early at the worksite so that you can become familiar with what needs to be completed .
- 7.2. Discuss any changes to spread field/water hole and cement pit locations . If necessary , drive to the spread field/water hole or pit and show the incoming operator the changes .
- 7.3. Review spread field map if one is available , this will ensure that there is no failure to communicate important changes to spread fields and cement pits . Have incoming operator sign off on spread field map .
- 7.4. If the truck is loaded at shift change , you must be sure to tell the incoming operator what product is on the truck and where it is going .
- 7.5. Review any problems with vacuum /water truck and equipment and record on the PMI .
- 7.6. Review previous shifts post trip inspection book for defects , start pre trip inspection for current shift .
- 7.7. It is very important that 2-man operations have regular and productive discussions regarding what they are expected to do for maintenance and cleaning of the equipment , well site trailers and jobs that need to be completed on the rig .
- 7.8. When working on a 2-man operation or when an operator has been out to relieve you for days off and you feel that they are not contributing their share to the maintenance and cleaning of the equipment , call your supervisor and ask them to become involved in resolving the issues .
- 7.9. **Silverpoint requires that there be an operator on site at all times to operate the vacuum truck . If the rig is shut down during your shift , authorization to leave early can only be given by the Drilling consultant .**

8. Swing Trucks

- 8.1. When working on shallow gas , or certain projects , there may be time when a swing truck will be needed to assist in hauling loads due to distance to the spread field , weather conditions and multiple rigs .
- 8.2. Both trucks are expected to work together to haul as many loads as possible while the swing truck is available . When working 12 hour shifts you are expected continue hauling loads , the swing truck is there to help you not replace you .

9. Have Respect for Other People and Their Property .

- 9.1. If the other operator is sleeping in the trailer during his 12 hrs off , be courteous and stay out of the trailer while he is sleeping .
- 9.2. If they have a satellite dish , take it down before moving the shack .
- 9.3. If you use their plates and utensils , clean them when you are finished . Keep the well site trailer clean .
- 9.4. Do not eat the other operators ' food . If you need cupboard space , ask the operator and he will make room for you .
- 9.5. **There is no smoking in Silverpoint Energy Services Trucks or Shacks**
- 9.6. When you are relieving an operator for days off feel free to clean and tidy up equipment but please leave tools and



3.02 Switching Out Operators

equipment in the same places as the original operator keeps them .

- 9.7. Do not rush switch outs, focus on last day. Don't rush just to get home, this is when things tend to be forgotten and accidents happen .

Remember : if you are in doubt about what to do, call your supervisor