

Required PPE:



Step	Image	Description	Hazard(s)	Original Severity	Original Probability	Original Risk	Control(s)	Mitigated Severity	Mitigated Probability	Mitigated Risk
1		Make Sure All Hoses and Hitch are on the Truck	Pintch Points, Lifting, Twisting, Pulling, Slips, Trips, and Falls	Serious Injury (Loss)	Highly Probable	Critical	Eng -Safety Pins for Hitch Admin - Lift With Your Legs, Ask for Help, Refer to SOP 1.11, Follow SOP PPE - CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection	Minor Injury (Loss)	Unlikely	Low
2		Make Sure Tank is Clean and Empty	Slips, Trips and Falls, Lifting, Twisting and Pintch Points	Serious Injury (Loss)	Highly Probable	Critical	Eng -Tank Bar Admin - Follow Procedures, 3 Point Contact, Watch Your Footing, Follow SOP PPE - CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection	Minor Injury (Loss)	Unlikely	Low
3		Remove All Personal Paper Work(Log Book etc.)	Ascending and Descending	Serious Injury (Loss)	Highly Probable	Critical	Eng -Hand Rails and Steps Admin - Refer to SOP 1.7, 3 Point Contact, Watch Your Footing, JTO and CORE PPE - CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection	Minor Injury (Loss)	Unlikely	Low

4		Make Sure Cab is Clean	Ascending and Descending	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Refer to SOP 1.7, 3 Point Contact, Watch Your Footing, JTO and CORE PPE - CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection	Negligible (First Aid)	Unlikely	Low
5		Fuel up Truck	Fuel Splashing in Your Eyes, Spills, Pinch Points	Serious Injury (Loss)	Highly Probable	Critical	Eng - Admin - Stay Focused on Task, Follow SOP, Don't Leave Unattended PPE - CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection	Negligible (First Aid)	Unlikely	Low

Created: 08/13/2026