

Required PPE:



Step	Image	Description	Hazard(s)	Original Severity	Original Probability	Original Risk	Control(s)	Mitigated Severity	Mitigated Probability	Mitigated Risk
1		Bump Test	Fumes	Serious Injury (Loss)	Highly Probable	Critical	1.Eng- Monitor, Harness, Lanyard 2.Adm-SOP, Core Training(H2S,confined space) 3.PPE-CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection, Harness, Lanyard, Monitor	Negligible (First Aid)	Unlikely	Low
2		Confined Space Paper Work	Information Overload, Never Performed Task, Unfamiliar to Paper Work	Serious Injury (Loss)	Highly Probable	Critical	1.Eng- 2.Adm-SOP, Core Training(H2S,confined space) 3.PPE-CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection, Harness, Lanyard, Monitor	Negligible (First Aid)	Unlikely	Low
3		Wear all Required PPE	Slips, trips & Falls	Serious Injury (Loss)	Highly Probable	Critical	1.Eng-Eng-Air Monitoring / Air Moving Equipment 2.Adm-SOP, Core TrainingH2S, Confined Space 3.PPE-CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection, Harness, Lanyard, Monitor	Negligible (First Aid)	Unlikely	Low

4		Report Problems	Personal Injury	Serious Injury (Loss)	Highly Probable	Critical	1.Eng- Harness and Lanyard 2.Adm- SOP, Use Proper Body Position, Core Training 3.PPE- CSA Approved Foot Wear, F/R Outerwear, Safety Glasses, Hardhat, Gloves, Hearing Protection if Needed, Harness, Lanyard, Monitor	Negligible (First Aid)	Unlikely	Low
---	--	-----------------	-----------------	--------------------------	-----------------	----------	---	------------------------	----------	-----