

## Service Schedule

The following table lists recommended service intervals for industrial motors.

Component	Inspection Interval	Replacement Interval
Motor Belt	3 Months	12 Months
Bearings	6 Months	24 Months
Wiring	6 Months	As Needed