



REF. NUMBER	PART NUMBER	PART NAME	QUANTITY Wt.Lbs.E	<u>a.</u>
1		TUB/SKID/UPRIGHT ASSEMBLY	1	
2	000018328	INFEED HOPPER ASSEMBLY	1	
	000010570 000010805 000010940 000010950 000010578	BOLTS: 1/2"-13 x 1 1/4" BOLTS 1/2"-13 NUTS 1/2" LOCK WASHERS 1/2" FLAT WASHERS 1/2" -13 X 2" BOLT	4 5 5 5 1	
3	000002676	SIDE OVERFLOW (OPTIONAL)	1	
	000010553 000010803 000010942	BOLTS: 3/8" - 16 X 1 1/4" BOLTS 3/8" - 16 NUTS 3/8" LOCKWASHERS	12 12 12	
4	000018424	TIP FRAME ASSEMBLY (OPTIONAL)	1	
	000010605 000010810 000010945	BOLTS: 3/4"-10 x 2" BOLTS 3/4"-10 NUTS 3/4" LOCK WASHERS	4 4 4	
DWG. NUMBER: PF	4420H1—1 BY:	JAF DATE: 3/31/06 REVISIONS	10/21/08 PAGE # 1	<u>'</u>

PROJECT: 44" X 20' TWIN	I BLADE MILL	Greystone	DESCRIPTION: OVERALL ASSEMBLY
REF. NUMBER	PART NUMBER	PART NAME	QUANTITY Wt.Lbs.Ea.
5	000018313	TUB FRAME UPRIGHT TOP SUPPORT	1
	000010605 000010810 000010945	BOLTS: 3/4"-10 x 2" BOLTS 3/4"-10 NUTS 3/4" LOCK WASHERS	2 2 2
6	000014069	SCREW SHAFT RH ASSEMBLY (complete)	1
7	000014039	SCREW SHAFT LH ASSEMBLY (complete)	1
8		DRIVE ASSEMBLY	1
9	000018330	DISCHARGE CHUTE ASSEMBLY (OPTIONAL)	1
	000010585 000010805 000010940	BOLTS: 1/2"-13 X 2 1/2" BOLT GR.5 1/2"-13 NUT GR.5 1/2" LOCK WASHER	2 2 4
10	000018286 000018287	MOTOR GUARD MOTOR GUARD FRONT ASSEMBLY MOTOR GUARD BACK ASSEMBLY	2 2
	000010570 000010805 000010940	BOLTS: 1/2"-13 X 1 1/4" BOLT 1/2"-13 NUT 1/2" LOCK WASHER	8 8 8
NOT SHOWN	000012799	BELLYPLATE SECTION #1	1
NOT SHOWN	000002653	BELLYPLATE SECTION #2	1
NOT SHOWN	000013182	BELLYPLATE DIVIDER	2
NOT SHOWN	000016060	PIPE PLUG 4" PVC	1
NOT SHOWN	000005588	PIPE CAP 6" PVC	2

SCREW TOTAL ESTAMATED WEIGHT




REF. NUMBER	PART NUMBER	PART NAME	<u>QUANTITY</u>	<u>Wt.Lbs.Ea.</u>
1	000012084	BEARING BOLTS:	2	
	000010620 000010810 000010945 000010955	3/4"-10 x 5" BOLTS 3/4"-10 NUTS 3/4" LOCK WASHERS 3/4" FLAT WASHERS	8 8 8 16	
2 3 4 5 6	000003532 000035320 000035290 000035221 000035140	BEARING SHIM (OPT.) (NOT SHOWN) WEAR SLEEVE LOWER STUB SHAFT SEAL SLINGER W/ COLLAR SEAL RETAINER PLATE NUTS:	2 2 2 2 2	
	000010805	1/2"-13 NUTS	10	
8 9	000035190 000035160	LOWER SEAL ADJUSTMENT PLATE ADJUSTMENT PLATE GASKET	2 2	
10	000030420	ADJUSTMENT PLATE WASHER BOLTS:	16	
	000030420 000010805 000010900	1/2"-13 x 2" BOLTS 1/2"-13 NUTS 1/2" WASHERS (RUBBER BACKED)	16 16 16	
11	0000015883 0000039026	LOWER STUB SHAFT W/O SLEEVE LOWER STUB SHAFT W/SLEEVE	2	
DWG. NUMBER: PF	4420H2 DRAWN BY:	JAF DATE: 3/31/06 REVISIONS	PAGE	# 1



REF. NUMBER	PART NUMBER	PART NAME	QUANTITY Wt.Lbs.Ea.
1	000012051	BEARING	2
	000010620 000010810 000010945 000010955	BOLTS: 3/4"-10 x 5" BOLTS 3/4"-10 NUTS 3/4" LOCK WASHERS 3/4" FLAT WASHERS	8 8 8 16
2	000031640	BEARING SHIM OPTIONAL (NOT SHOWN)	2
3	000011956	UPPER STUB SHAFT ASSEMBLY	2

DWG. NUMBER: PF4420H3 BY: JAF DATE: 3/31/06 REVISIONS PAGE # 1



LH PITCH SCREW SHAFT

REF. NUMBER	PART NUMBER	PART NAME	QUANTITY	Wt.Lbs.Ea.
1	000039026	LOWER STUB SHAFT ASSEMBLY	2	
2	000011956	UPPER STUB SHAFT ASSEMBLY BOLTS: (PER STUB SHAFT)	2	
	000010720 000010860 000010947	7/8"-14 x 3 1/2" BOLTS Gr.8 7/8"-14 NUTS Gr.8 7/8" LOCK WASHERS	12 12 12	
3 4 5	000014037 000014038 000033140 000033668 000013792	RH SCREW SHAFT w/FLIGHTS & BASES RH SCREW SHAFT w/SHOES & PADDLES FLIGHT RH FLIGHT GUSSET WEAR SHOE RH (NI—HARD)	4 8 48	
6 4 7	000014067 000014068 000033142 000033668 000013791	LH SCREW SHAFT w/FLIGHTS & BASES LH SCREW SHAFT w/SHOES & PADDLES FLIGHT LH FLIGHT GUSSET WEAR SHOE LH (NI-HARD)	4 8 48	
	000010581 000010805 000010940 000010950	BOLTS: (PER WEAR SHOE) 1/2"-13 X 2" SLOT-HEAD BOLTS 1/2"-13 NUTS 1/2" LOCKWASHERS 1/2" FLAT WASHERS	2 2 2 2	
8	000034606	PADDLE BASE	78	
9	000034730	PADDLE NI-HARD	78	
	000010725 000010860 000010840 000010920	BOLTS: (PER PADDLE) 7/8"-14 X 4" BOLT Gr.8 7/8"-14 NUTS Gr.8 7/8"-14 JAM NUTS 7/8" FLAT WASHER	3 3 3 3	
SCREW SHAFT RH ESTIMATED WEIGHT SCREW SHAFT LH ESTIMATED WEIGHT				

DWG. NUMBER:PF4420H5— BY: JAF | DATE: 3/31/06 | REVISIONS | 10/21/08 | PAGE # 1

