	ASSURANCE CONSTRUCTION & SERVICES	ESS	SMENT & ANALYSIS WORKSHEET WELDING, CUTTING & BURNING							R-15 FORMAL HAA		
	JOB/TASK  ANALYSIS BY  HARLEY WINBORN  SIGN			W	ELDI	SENIOR ADMINISTRATOR JASON DE BOER						
	ORIGINAL ASSESSMENT DATE  01/01/2011	FOR TH	THIS REVISION (ANN. REVIEW, CHANGE IN PROCEDURE, CHANGE OR NEW EQUIP., OR INCIDENT)  ANNUAL REVIEW									
	TOOLS/EQUIPMENT USED			MATERIALS REQUIRED					MSDS	PPE REQUIRED		
WHAT YOU NEED	TANKS, TORCHES, HOSES, REGUILATORS, BENCH, CLAMPS, MIG	OXYGEN, ACETYLENE, WIRE, ELECTRODS, ARGON, CO2,				ARGON,			WELDING MASK, RESPIRATOR			
HAZARDOUS STEPS & TASKS	STEPS /TASKS	WHAT COULD	LD HAPPEN		HEALTH HAZ.	SAFETY HAZ.	PROP/EQUI P DAMAGE/LO S		WHAT PROTECTS YOU	ENG. CONTROL	ADMIN. CONTROL	P.P. EQUIP.
	AUTHORIZATION - HOT WORK PERMIT											
	PPE	VARIOUS SERIOUS INJURIES				Х					Х	Х
	WORKSITE AWARENESS											
	EQUIPMENT LEAKS	FIRE, EXPLOSION				Х	Х	CONTROLS				
	VENTILATION	WELDING FUMES, SUFFOCATION			Х	Х						
	OTHER WORKERS NEARBY	BURNS				Х						
	CONFINED SPACE	FIRE, BURNS, SUFFOCATION			Х	Х	Х					
		<u> </u>										
	FIRE PREVENTION & PROTECTION	<del> </del>										
	AVAILABILITY OF FIRE FIGHTING EQUIPMENT	FIRE				Х	Х	Ω	SWP, VENTILATION (OPEN DOOR), SAFETY GLASSES, WELDING MASK, GLOVES,	x	x	x
	COMBUSTIBLE MATERIALS & VAPOURS	FIRE, EXPLOSION				X	X	AR	COVERALL, BOOTS, ATMOSPHERIC TESTS	^	^	^
	WORKING OVERHEAD	FALLING MATERIAL				X	X	HAZ/				
	WORKING OVERHEAD	FALLING MATERIAL				X						
		<u> </u>										
	SAFETY GUIDELINES							_				
	PROTECT CABLES & HOSES	FIRE, EXPLOSION				х	Х					
	CABLES AROUND BODY PARTS	TRIP/SLIP, FALL				X						
					† † †							
RATING SYSTEM	PROBABLILITY/RISK RATING WITHOUT CONTROLS OR I		SEVERITY/CONSEQUENCE RATING									
	1 LOW PROBABILITY (EXTREMELY REMOTE)			FIRST AID ONLY/M		TOTALS		RISK				
	2 LOW-MEDIUM PROBABILITY (REMOTE) 3 MEDIUM PROBABILITY (MIGHT OCCUR) 4 MEDIUM-HIGH PROBABILITY (LIKELY WILL OCCUR EVENTUALLY)			MEDICAL AID/MING				RATING /20				
				PERMANENT DISA								
	5 HIGH PROBABILITY ( WILL OCCUR )	5									<b>─ 13</b>	
	2 HEALTH	-	HEALTH				10					
	3 SAFETY	<u>ა</u> 5	SAFETY							<b>→</b>		

Welding, Cutting & Burning HAA