



no-melt anneal, 1100 K, 5E6 steps

anneal-short crystal melt, 3000 K, 8E3 steps quench 3000-1100, inst. anneal, 1100 K, 5E5 steps