```
* USART3_asynch_transmit.h
 * Created: 4/26/2022 8:06:04 PM
 * Author: jason
#ifndef USART3_ASYNCH_TRANSMIT_H_
#define USART3_ASYNCH_TRANSMIT_H_
#define F_CPU 4000000
#define USART3_BAUD_RATE(BAUD_RATE) ((float)(F_CPU * 64 / (16 *(float)BAUD_RATE))) //>
  Calculation of baud rate from data sheet
#include <avr/io.h>
#include <util/delay.h>
#include <string.h>
//Header functions
void USART3_sendChar(char c);
void USART3_init (uint16_t, uint8_t, unsigned char);
void USART_sw_write(char);
//A simple function to configure a USART might have a single parameter that
//specifies the desired baud rate. The function that you must write for this task
//goes further than that, it allows both baud rate and the frame format to be
  specified
void USART3 init (uint16 t baud, uint8 t data bits, unsigned char parity){
    PORTB_DIR |= PINO_bm; //To transmit the data
    //Specify the baud rate value for the USART3
    USART3.BAUD = (uint16_t)USART3_BAUD_RATE(baud);
    //Initialize the data bits and the parity bits type
    USART3 CTRLC |= data bits | parity;
    USART3.CTRLB |= USART_TXEN_bm; //Enable USART transmitter
}
//To be able to send the string of characters
void USART3_sendString(char* input){
    for(size_t i = 0; i < strlen(input); i++){</pre>
        USART_sw_write(input[i]);
    }
}
//Function to be able to transmit characters
//to the TX pin and display on the Tera Term
void USART_sw_write(char c)
```

```
2
```

```
...imodule_LED_CO2_Level_Lab11Task2\USART3_asynch_transmit.h
    //Poll until the transmit buffer register are empty
    //when they contain data that has not been moved to
    //transmit shift register
    while (!(USART3.STATUS & USART_DREIF_bm))
        ;
    }
    //Load data to transmit shift register and
    //output each of the bits serially to the TXD pin
   USART3.TXDATAL = c;
}
#endif /* USART3_ASYNCH_TRANSMIT_H_ */
```